



United States  
Enrichment Corporation


July 12, 1995  
USEC-95-014

United States  
Enrichment Corporation

2 Democracy Center  
6903 Rockledge Drive  
Bethesda, MD 20817

Tel: (301) 564-3200  
Fax: (301) 564-3201

Mr. Michael Murphy  
United States Environmental Protection Agency  
Region V  
77 West Jackson Boulevard  
AT-18J  
Chicago, Illinois 60604-3590



Dear Mr. Murphy:

Final Report on NESHAP Audit Findings

As discussed in our May 10, 1995 correspondence to you, one corrective action remained to be completed before July 1995 in order to close all corrective actions identified from the March 16 through 19, 1993 NESHAP inspection of the Portsmouth Gaseous Diffusion Plant (this being to minimize line bends and tubing length at Sampler Location #9).

At Sampler Location #9, system sampling points were relocated to shorten the collection line and still provide system accessibility. The collection trap train was rotated 180 degrees to decrease line length and bends. With these modifications to correct the NESHAP audit finding, Unit #9 became operational as of 1525 hours on June 16, 1995. The removed items were rinsed and will become part of the yearly venting value.

All corrective actions identified for compliance with 40 CFR 61, Subpart H, National Emission Standards for Emission of Radionuclides Other Than Radon from Department of Energy Facilities were completed as of June 16, 1995. If you have comments or questions, please contact me at (614) 897-2144. (We look forward to seeing you sometime in August.)

Sincerely,

Mary E. Young  
USEC Environmental Compliance  
Site Representative

MEY:bjt

cc:  
Eugene Gillespie, DOE-PORTS  
Melda Rafferty, DOE-PORTS  
T. Michael Taimi, USEC-HQ  
Ken Tomko, LMUS-PORTS